

Table 8
Findings of Suitability for Early Transfer
Summary of Asbestos Containing Materials Building Survey
Fort McClellan, Alabama
Page 1 of 2

Building Number	Year Built	Description	Description & Location of ACM	Condition
336	1941	Heating Plant Building	Friable, air-cell type asbestos containing insulation compound is applied to 6-inch pipes located in the building. White cementitious asbestos containing insulation is found on 12-inch piping located in the building.	Fair
1617	1941	US Army Center	Non-friable 12 x 12-inch floor tile mastic found in the building.	Good
1696	1941	Vehicle Maintenance Shop	Asbestos containing transite siding is found on the exterior of the building.	Good
1697	1941	Storage Group Installation	Asbestos containing transite siding is found on the exterior of the building	Good
1740	1936	Chapel	Non-friable presumed asbestos containing 12x12 and 9x9-inch floor tile and mastic.	Good
2109	1970	Exchange Auto Service	Non-friable asbestos containing 12 x 12-inch floor tile and mastic is found in the building.	Good
3137	1988	Transient Quarters	Non-friable presumed asbestos containing 12x12-inch floor tile and mastic.	Good
3138	1954	Vehicle Maintenance Shop	Friable, white cementitious asbestos containing insulation is found on pipe fittings located throughout the building.	Good
3172	1969	Working Animal Building	Non-friable presumed asbestos containing 12x12-inch floor tile and mastic.	Good

Table 8
Findings of Suitability for Early Transfer
Summary of Asbestos Containing Materials Building Survey
Fort McClellan, Alabama
Page 2 of 2

Building Number	Year Built	Description	Description & Location of ACM	Condition
3174	1959	Storage Group Installation	Non-friable presumed asbestos containing 12x12-inch floor tile and mastic.	Good